

NW 142nd Terrace Drainage Project



All the pictures on this page illustrate the flooding and ponding of the roadway after a moderate rainfall has occurred.



Merrillwood Stormwater System Improvements



The pictures above and below show access to the existing basin. Note in the picture below that access is only achieved through the driveway or to the left of the pine trees.

